DOORS & WINDOWS

Uninsulated Steel Fire Door

钢制非隔热防火门

A fire-integrity test report for a steel fire door with no insulation classification. The report states E60 (i) under GB/T 38252-2019.

Document number	CBT10502182076
Issue date	2025-11-18
Standards	GB/T 38252-2019
Applicant / holder	浙江艾绿净化科技有限公司
Issuing organization	广东省宝通质量检测有限公司

Recorded Results

Tested specimen	900 x 2100 mm; one door set
Reported fire-integrity designation	E60 (i) under GB/T 38252-2019
Recorded duration	60 min
Observed result	No flames on the unexposed side; no cracks; no loss of fire integrity
Report conclusion	Meets the E60 (i) criteria stated in the report

Sample and Test Conditions

Client-submitted specimen received 10 November 2025. Testing took place 13-18 November 2025.

The complete source contains the furnace-temperature curve and before/after specimen photographs.

Scope of This Document

This is an integrity-only result for an uninsulated door. E60 (i) is not presented as EI60, and no insulation performance is added.

Read the complete Chinese document for the original tables, drawings, seals and stated conditions.